## STATE OF CONNECTICUT





## DEPARTMENT OF ENVIRONMENTAL PROTECTION

**DEP Case Number: 20013086** ITA Number: SPL0020474EH



## REPORT OF PETROLEUM OR CHEMICAL PRODUCT DISCHARGE, SPILLAGE, SEEPAGE, FILTRATION

The following information is submitted concerning petroleum or chemical product discharge reported verbally to the Department of Environmental Protection / State Police at Pratt & Whitney, East Hartford, CT on 5/7/01 at 1:19 pm

(location)

(date)

(time)

John M. Wotus . by

(name)

RCRA RECORDS CENTER FACILITY Fra! (Whitney MANS) I.D. NO. CTD99067208 FILE LOC. R-IC OTHER ROMS# 101380

1. Time and date of discharge, spillage, etc:

Leak discovered on 5/7/01 at approximately 7:45 a.m.. Leak could have started on 5/4/01, but facility was not aware of incident.

2. Location to include town, river, highway, distance from intersection, etc., of the pollution or contamination:

Spill occurred on State owned property for UConn Stadium adjacent to Silver Lane in East Hartford. Property is located on portion of former airport previously owned by United Technologies, Pratt & Whitney, 400 Main St. E. Hartford, CT, 06108

- 3. Type of oil, petroleum or chemical pollutant or contaminant: Assumed to be paint/solvent type material – liquid/sludge
- 4. Quantity of discharge, spillage, seepage, filtration:

Approximately ½ gallon

Form Number: EH EHS 0034 Revision Date: Initial Issue Date Issued: 3/21/00 Page 1 of 2

- 5. Cause of pollution or contamination:
  - a. Type of vessel, vehicle, containers, etc., which contained the pollutant or contaminant: 55-gallon metal drum
  - b. Describe in detail what actually occurred to cause discharge, spillage, seepage, and filtration:

    Drum found during excavation activities for Stadium construction. Drum was on State property.

    Pratt & Whitney provided services for removal and cleanup. Drum damaged by bulldozer

    causing drum to slowly leak (viscous). Drum assumed to be underground prior to discovery.

    When discovered, the material was not known and it was thought that material could have been rusty water. Upon sampling, the material was then noted as being paint type material.
  - c. If pollutant or contamination was a result of discharge, spillage, seepage or filtration from a moving vehicle or vehicle, give location of departure and destination:

N/A

- 6. Name and address of owner of ship, boat or other vessel, terminal, establishment, vehicle, trailer or machine causing such pollution or contamination:
  Pratt & Whitney, 400 Main Street, East Hartford, CT, 06108 and State of CT Office of Policy and Management.
- 7. Name and address of person making this report:

  John M. Wotus Pratt & Whitney 400 Main Street, East Hartford, CT, 06108
- 8. Title, or relationship to owner, of person making report:

  P&W Environmental Project Engineer

All statements contained herein are true to the best of my knowledge.

Form Number: EH EHS 0034 Revision Date: Initial Issue Date Issued: 3/21/00

Page 2 of 2

Signature of person making report

Form Number: EH EHS 0034 Revision Date: Initial Issue Date Issued: 3/21/00 Page 3 of 2